

6000counts

Automatic Identification Digital Clamp Meter Instruction Manual

Index






1. Overview.....	1
2. Safety precautions.....	1
3. Characteristics.....	1
4. Operation panel instructions.....	3
5. Technical Specifications.....	4
6. Automatic switch machine.....	9
7. Troubleshooting.....	9

1. Overview

The 6000counts is a pocket-sized 3 5/6-digit RMS auto-scanning digital meter that does not require a dial to select a function. The meter will automatically recognize and measure based on the input voltage/current/resistance/current. It has stable performance, high precision, high reliability, clear reading and overload protection. Driven by AAA 1.5V battery, the instrument adopts large screen LCD display and adopts boost power supply. Even at the edge of 2.3V low battery, it can ensure the high brightness of backlight and flashlight. The meter is easy to carry and is very popular among users. The instrument's backlight can be turned on and off automatically after 15 seconds. This series of instruments can be used to measure DC voltage and AC voltage, AC current 600A, resistance, capacitance, diode, temperature, continuity test, square wave output, frequency measurement and true RMS. It is a superior tool and an ideal tool for laboratories, factories, radio enthusiasts and families.


2. Safety Precautions

This series of instruments is designed in accordance with IEC1010 (Safety Standards promulgated by the International Electrotechnical Commission), please read the safety precautions before use.

1. When measuring voltage, please do not input the limit voltage exceeding the effective value of DC 700V or AC 500V;
2. The voltage below 36V of the current file is a safe voltage;
3. When changing functions and ranges, the test pen should leave the test point;
4. Select the proper function and range, beware of wrong operation, although the series of instruments with a full-range protection, but for safety reasons, you still pay more attention;
5. Safety Symbol Description: “” Exist dangerous voltage, “” Ground, “” Double insulation, “” Operator must refer to the instruction manual, “” Low voltage symbol.

3. Characteristics

1. General Characteristics

- 1-1. Display: liquid crystal display (LCD);
- 1-2. Maximum display: 5999 (5 5/6) bit automatic polarity display;
- 1-3. Measurement method: double integral A/D conversion;
- 1-4. Sampling rate: about 3 times per second;
- 1-5. Over range display: The highest position shows “OL”;
- 1-6. Low voltage display: “” symbol appears;
- 1-7. Working environment: (0~40)°C, relative humidity < 80%;
- 1-8. Power: AAA 2* 1.5V battery;
- 1-9. Volume (size): 176×67×33mm (L×W×H);

1-10. Weight: about 300g (including 1.5V battery);

1-11. Attachment: One instruction manual, one certificate, one outer packaging box, one pair of test leads, two AAA1.5V batteries.

2. Technical characteristics


2-1. Accuracy: $\pm(a\% \text{ of reading} + \text{least significant digit})$, to ensure accuracy Ambient temperature: $(23 \pm 5)^\circ\text{C}$, relative humidity $<75\%$, calibration guarantee period from the date of manufacture for one year.

2-2. Performance (Note "▲" indicates that the meter has this function)

Function	
DC voltage DCV	▲
AC voltage ACV	▲
DC current DCA	▲
AC current ACA	▲
Resistor / Diode / On-Off Test / Capacitor	▲
Frequency F	▲
Square wave output	
NCV	▲
Zero line / Fire line test	▲
Full unit symbol	▲
Backlight manual/Auto off	▲
True RMS measurement	▲
Temperature ($^\circ\text{C}/^\circ\text{F}$)	▲
Flashlight lighting	▲

4. Operation panel instructions

1. Opening of tong head;
2. High current test center;
3. Product model label position;
4. Current measuring wrench;
5. Long press for power on and off, short press for DC voltage / AC voltage / Resistance / buzzer / diode / temperature / frequency function switch key;
6. Long press is the key to turn on the flashlight; short press is the reset key of DC current and capacitance;
7. Electric field measurement (NCV) / neutral wire measurement (LIVE);
8. The hold key is the data holding key. Long press for 2 seconds to turn on the backlight;
9. LCD display window;
10. Com input terminal; negative input terminal, Insert Black probe;
11. Voltage, resistance, frequency, temperature, diode, capacitor, buzzer input port.



5. Technical Specifications

1. DC voltage / AC voltage automatic scanning test (DCV / ACV)

Accuracy Range	6000counts	Resolution
DC/AC6V	± (0.5%+3)	0.001V
DC/AC60V		0.01V
DC/700V		0.1V
AC500V	± (0.8%+10)	1V

Input impedance: 10M Ω ; overload protection: 700V DC or 500V AC peak.

The specific operations are as follows:

1-1. Long press POWER is greater than 2S, the boot display is automatically scanned state "----".

1-2. Insert the black test lead into the "COM" jack and the red test lead into the "V/ Ω " jack; the test leads are reliably in contact with the test point.

1-3. When the measured voltage between the input port "COM" and "VR" is greater than 0.6V, regardless of the AC voltage or DC voltage, the meter will compare the DC component with the AC component, take the larger component signal, and then measure according to the measurement. The value is automatically switched between 6V/60V/600V/DC700V (AC500V) and the measured value is displayed on the LCD.

Note:

1) The input voltage must not exceed DC700V or AC500V. If it exceeds, there is danger of damage to the instrument circuit. When high voltage circuit, pay special attention to avoid electric shock;

2) After completing all measurement operations, disconnect the test leads from the circuit under test.

2. Resistance (Ω)

Accuracy Range	6000counts	Resolution
600 Ω	± (0.8%+3)	0.1 Ω
6k Ω		1 Ω
60k Ω		10 Ω
600k Ω		100 Ω

4/9

6M Ω	± (2.5%+3)	1k Ω
60M Ω		10k Ω

Input impedance: 10M Ω ; overload protection: 700V DC or 500V AC peak.

The specific operations are as follows:

2-1. The boot display is in the automatic scan status "----".

2-2. Insert the black test lead into the "COM" jack and the red test lead into the "V/ Ω " jack; the test leads are reliably in contact with the test point.

2-3. If the measured resistance at both ends of the test leads is less than 50 Ω , the beep will emit a continuous sound, which requires a fast buzzer measurement. Press the power button to enter the buzzer for quick measurement.

2-4. If the closed loop resistance is measured, the resistance across the resistance to be measured must be discharged. Otherwise, if the voltage in the loop is greater than 0.6V, the meter will mistakenly consider the voltage measurement and enter the voltage measurement mode.

2-5. Input the resistance measurement value between the input port "COM" and "V/ Ω ". The meter will automatically switch between 600 Ω /6k Ω /60k Ω /600k Ω /6M Ω /60M Ω according to the measured value of the resistance, and then the measured value will be on the LCD.

Note:

1) When measuring low resistance, the test leads will bring internal resistance. To obtain accurate reading, you can record the short value of the test lead first, and subtract the value when the test lead is shorted in the measurement reading;

2) When measuring the line resistance, all the power of the circuit under test must be turned off and all capacitors should be completely discharged to ensure the correct measurement value;

3. Fast continuity test / diode / capacitor

Range	display value	test condition
"----"	Diode forward voltage drop	Forward DC current is about 1mA, open circuit voltage is about 3V
	The buzzer sounds long and the resistance of the test is less than (50 \pm 20) Ω .	Open circuit voltage is about 0.4V, press "power" for two-speed function switching

5/9

4. Capacitance(C)

Accuracy Range	6000counts	Resolution
10nF	$\pm (3.5\%+20)$	10pF
100nF		100pF
1uF		1nF
10uF		10nF
100uF		100nF
1mF		1uF
10mF		10uF
60mF	$\pm (5\%+3)$	100uF

Overload protection: 700V DC, 500V AC peak.

4-1. The boot display is in the automatic scan status "----".

4-2. Insert the black test lead into the "COM" jack and the red test lead into the "V/ Ω " jack; the test leads are reliably in contact with the test point.

4-3. For fast on/off test/diode/capacitance measurement, continuously trigger the "power" switch to enter the fast on/off test/diode/capacitance measurement in the second cycle, and select the corresponding function measurement according to the measurement requirements. When measuring the capacitance, the size of the measured capacitance will automatically select different ranges, and the measured value will be displayed on the LCD. The capacitance measurement file is 10nF/100nF / 1uF/10uF/100uF/1mF/10mF/60mF.

Note:

- 1) When measuring capacitance with 10nF file, there may be residual reading on the screen display value. This number is the distributed capacitance of the test pen. It is an accurate reading and can be subtracted after measurement.
- 2) When the large capacitance file measures severe leakage or breakdown capacitance, some values will be displayed and unstable; when measuring large capacitance, the reading takes several seconds to stabilize, which is normal when measuring large capacitance;
- 3) Please fully discharge the capacitor before testing the capacitor capacity, otherwise it will enter the voltage measurement mode.
- 4) Unit: 1F=1000mF, 1mF=1000uF, 1uF=1000nF, 1nF=1000pF

5. AC and DC current

Accuracy Range	6000counts	Resolution
60A	$\pm (2.5\%+30)$	0.01A
600A		0.1A

Maximum measured voltage drop: 600mV; overload protection: 10A

The specific operations are as follows:

5-1. Press the handle 10, slowly open the jaw opening according to the size of the measuring wire diameter, and pass any one of the measured current wires vertically through the center of the clamp head. The meter will automatically switch to the corresponding according to the measured current. As shown in Figure 1, the measured current value and the current polarity of the red test point will be displayed on the screen at the same time. The clamp can only measure one conductor at a time. If two or more conductors are measured at the same time, the measurement reading will be wrong.

5-2. In the current measurement state, the measurement meter should be unplugged between "VR" and "COM" due to the large measurement current.

5-3. The automatic identification current must be greater than 0.2A;

Note:

- 1) The maximum input current is 600A (depending on the red pen insertion position), and an excessive current will display OL.

6. NCV measurement;

The operation is as follows:

6-1. Press and hold the "NCV" button; enter the EF measurement.

6-2. The front end of the meter has NCV test points. As long as the point is close to the AC voltage, the buzzer will emit different continuations according to the different strength of the signal, and the LCD will also display according to the strength of the signal. Different number of segments.

7. Temperature measurement (° C/° F)

Accuracy Range	6000counts	Resolution
(-20-1000)°C	$\pm (1.0\%+5) < 400^{\circ}\text{C}$; $\pm (1.5\%+15) \geq 400^{\circ}\text{C}$	1°C
(0-1832)°F	$\pm (0.75\%+5) < 750^{\circ}\text{F}$; $\pm (1.5\%+15) \geq 750^{\circ}\text{F}$	1°F

The operation is as follows: (top right)

7-1. Dial to the "TEMP" file;

7-2. Insert the two input ends of the temperature probe into the "V/ Ω /Hz" and "COM" terminals of the red test pen. The test probe is inserted into the measured water, and the temperature of the measured water will be displayed on the LCD.

7-3. Press the SELECT button to toggle between Centigrade and Fahrenheit ($^{\circ}$ C/ $^{\circ}$ F).

8. Frequency measurement

Accuracy Range	6000counts	Resolution
10Hz	$\pm (0.1\%+3)$	0.01Hz
100Hz		0.1Hz
1kHz		1Hz
10kHz		10Hz
100kHz		100Hz
1MHz		1kHz
10MHz		10kHz

Input sensitivity: 1V rms; overload protection: 550V DC or AC peak (no more than 10 seconds)

Frequency measurement

1. trigger power key; switch to frequency measurement function;
2. insert pen or shield cable into "COM" and "V/ Ω /Hz" jack;
3. Measurement values will be displayed on the LCD.

Note:

- 1) When the input exceeds 10Vrms, it can be read, but the error may be larger;
- 2) In a noisy environment, it is best to use a shielded cable when measuring small signals;
- 3) When measuring high voltage circuits, special care should be taken to avoid electric shock;
- 4) It is forbidden to input voltage values exceeding 250V DC or AC peak to avoid damage to the meter.

6. Automatic switch machine

When the meter is stopped for about 15 minutes, the meter will automatically power off and enter the sleep state; if you want to restart the power, press and hold the "power" button for more than 2 seconds, the LCD will display "----" for automatic scanning. The auto power off symbol "APO", press and hold the "hold" button, and turn on the power switch at the same time, the auto power off function will be canceled, and there is no "APO" symbol on the screen. When the symbol disappears, the auto power off function will be canceled.

7. Troubleshooting

If your instrument does not work, the following method can help you solve the general problem, if the fault still can not be excluded, please contact the service center or dealer.

Failure phenomenon	Inspection site and method
Not shown	Battery not connected
Low battery symbol	Replace the battery
Current is not input	Replace the battery
Resistance display error	Replace fuse
	The test pen is not in contact

This manual is subject to change without notice;

The contents of this manual are considered correct. If the user finds any errors, omissions, etc., please contact the manufacturer;

The company does not bear the accidents and hazards caused by the user's wrong operation;

The functions described in this manual are not intended to reasons of the product for special purposes.