User Manual



All rights reserved.
Specifications are subject to change without notice.

LIMITED WARRANTY AND LIMITATION OF LIABILITY

Customers enjoy one-year warranty from the date of purchase.

This warranty does not cover fuses, disposable batteries, damage from misuse accident, neglect, alteration, contamination, or abnormal conditions of operation or handling, including failures caused by use outside of the product's specifications, or normal wear and tear of mechanical components.

Introduction	1
Safety Information	1
Instrument Overview	3
LCD Display	3
Function Buttons	5
Rotary Buttons	6
Input Terminals	8
Measurements Instruction	9
Measure AC/DC Voltage	9
Measure AC/DC Current	9
Measure Resistance	10
Test Diodes and Continuity	10
Measure Capacitance	11
Measure Frequency and Duty Cycle	12
Measure Temperature	
Test NCV	

V.F.C test	14
V.F.C test	11
Square wave test	14
Maintenance	15
Clean the Product	15
Replace the Batteries	15
Replace the Fuses	16
Specifications	17
General Specifications	17
Mechanical Specifications	17
Environmental Specifications	
Electrical Specifications	18

Introduction

This product is a 9999 counts true RMS autoranging digital multimeter.

Safety Information


To avoid possible electrical shock, fire, or personal injury, please read all safety information before you use the product. Please use the product only as specified, or the protection supplied by the product can be compromised.

- Examine the case before you use the product.
 Look for cracks or missing plastic. Carefully look at the insulation around the terminals.
- The measurement must be made with correct input terminals and functions and within the allowable measuring range.
- Do not use the product around explosive gas, vapor, or in damp or wet environments.

- Keep fingers behind the finger guards on the probes.
- When the product has already been connected to the line being measured, do NOT touch the input terminal that is not in service.
- Disconnect the test leads from the circuit before changing the mode.
- When the voltage to be measured exceeds 36V
 DC or 25V AC, the operator shall be careful enough to avoid electric shock.
- Misuse of mode or range can lead to hazards, be cautious. " [][" will be shown on the display when the input is out of range.
- Low level of a battery will result in incorrect readings. Change the batteries when battery level is low. Do not make measurements when the battery door is not properly placed.

Instrument Overview


LCD Display



1	AUTO	Auto range. The product selects the range with the best resolution.
(2)	MANU	Manual range. The user selects the range.
(3)	F	Capacitance test. (Farad)
4	^	Relative mode.
(5)	*	Diode test.
6	•)))	Continuity test.
7	%	1. toot
8)	-8888	Secondary measurements display.
9	AC	Alternating current.
(10)	DC	Direct current.
(10)	DO	3


(11)	Hz	Frequency test. (Hertz)		
12	°C	Temperature test. (Celsius)		
(13)	°F	Temperature test. (Fahrenheit)		
14)	- humainmadamadamada	Analog bar graph.		
15)	Ω	Resistance test. (Ohm)		
16)	A	Current test. (Ampere)		
17)	V	Voltage test. (Volt)		
18	-0.0.0.0	Primary measurement display.		
19	T-RMS	The product measures both sinusoidal and nonsinusoidal ac waveforms accurately.		
20	①	Low battery. Replace batteries.		
21)	-	Negative readings.		
22	HOLD	Display freezes present reading.		
23	V.F.C	Frequency converter test.		
2	MAX	Display maximum value.		
23	MIN	Display minimum value.		
nk	Measurement units.			

Function Buttons



- Short press to switch among functions. Long press to enter in V.F.C function.
 - Short press to change range.
- Push for more than 2 seconds to enter the relative mode. The product will store the present reading as a reference for subsequent readings. The display is zeroed, and the stored reading is subtracted from all subsequent readings. Longpush again to exit the relative mode.
- Press this button to switch MAX/MIN test. Long press 2 second to quit MAX/MIN mode.
- Push once to hold the current reading on the display; push again to continue normal operation. Long press beyond 2 seconds to turn on flashlight; long press again to turn off flashlight.

Rotary button



Turn off the product at this position.

- The product automatically powers off after 15 minutes of inactivity.


 The product automatically powers of after 15 minutes of inactivity.

 The product automatically powers of after 15 minutes of inactivity.
- The built-in beeper beeps 5 times
 1 minute before auto power off.
- To restart the product from auto power off, press the SELECT button or turn the rotary switch back to the OFF position and then to a needed position.
- To disable the Auto Power Off function, hold down the SELECT button when turning on the product, you will hear five beeps if you have successfully disabled the function.

OFF

V.F.C % ₹ Hz V	AC voltage ≤750V DC voltage ≤1000V Frequency ≥10V, 1~100KHz Duty cycle: 1%~99% V.F.C		
% ~ 0	AC voltage ≤99.99mV DC voltage ≤99.99mV Frequency ≤10V, 1~10MHz Duty cycle: 1%~99% Temperature: 20~1000° C (-4~1832)°F		
Δ (1)	Resistance: ≤99.99MΩ Continuity: beeper will beep when resistance less than 50 Ω Diode test. Displays ① above 3V Capacitance: ≤9.999mF		
NCV	NCV		
ЛДоит	Square wave: 50Hz/100Hz/200Hz/300Hz/400Hz/ 500Hz/600Hz/700Hz/800Hz/900Hz/ 1000Hz/2000Hz/3000Hz/4000Hz/ 5000Hz		
₩Ã	DC current: ≤99.99mA. AC current: ≤99.99mA.		
μÃ	DC current: ≤999.9 μ A. AC current: ≤999.9 μ A.		
Ã	DC current: ≤9.999A AC current: ≤9.999A		

Input Terminals



A	Input terminal for AC/DC current measurements to 9.999A.
μ A/mA	Input terminal for AC/DC current measurements to 99.99mA.
COM	Common (return) terminal for all measurements.
₩-«)JM-8 VΩHz-IF	Input terminal for the measurements of: 1. Diode 2. Continuity 3. Square wave 4. Temperature 5. AC/DC voltage 6. Resistance 7. Frequency 8. Capacitance

Measurements Instruction

Measure AC/DC Voltage

- Connect the black test lead to the COM Terminal and the red lead to the *** Terminal.
- Touch the probes to the correct test points of the circuit to measure the voltage.
- 4. Read the measured voltage on the screen.

*Do not measure voltage that exceeds the extremes as indicated in the Specifications.

*Do not touch high voltage circuit during measurements.

Measure AC/DC Current

- Connect the black test lead to the COM Terminal and the red lead to the A or µA /mA Terminal (choose based on the value of the current to be measured);
- 2. Turn the rotary to A, a or A;
- Break the circuit path to be measured, connect the test leads across the break and apply power;
- 4. Read the measured current on the display.

*Do not measure current that exceeds the extremes as indicated in the Specifications.

*Use the AmA Terminal when you are measuring an unknown current. Then switch to the µA Terminal if necessary.

*Do not input voltage at this setting.

Measure Resistance

- Touch the probes to the desired test points of the circuit to measure the resistance;
- 4. Read the measured resistance on the display.

*Disconnect circuit power and discharge all capacitors before you test resistance.

*Do not input voltage at this setting.

Test Diodes and Continuity

- Connect the black test lead to the COM Terminal and the red lead to the ^{*******} Terminal;
- 2. Turn the rotary to $\frac{1}{\Omega}$, press "SELECT" to the continuity Mode;
- To test continuity, touch the probes to the desired test points of the circuit. The built-in beeper will beep when there is a short circuit;

4. To test diodes, connect the red probe to the anode side and the black probe to the cathode side of the diode being tested. Then read the forward bias voltage value on the display. If the polarity of the test leads is reversed with diode polarity or the diode is broken, the display reading shows "OL".

*Do not input voltage at this setting.

*Disconnect circuit power and discharge all capacitors before you test diode.

Measure Capacitance

- Connect the black test lead to the COM Terminal and the red lead to the *** Terminal;
- Turn the rotary to ^{*}_Ω, press "SELECT" to the capacitance Mode;
- Connect the red probe to the anode side and the black probe to the cathode side of the diode being tested;
- Read the measured capacitance value on the display once the reading is stabilized.

*Disconnect circuit power and discharge all capacitors before you test diode.

Measure Frequency and Duty Cycle

- Connect the black test lead to the COM Terminal and the red lead to the *** Terminal;
- Turn the rotary switch to , press SELECT to frequency test function (≥10V , 1~100KHz); or turn the rotary switch to , press SELECT to frequency test function (≤10V , 1~5MHz);
- 3. If the frequency between 100kHz and 5MHz, press SELECT to enter AC mV position. Touch the probes to the desired test points, now the vice display will show frequency; Then press the SELECT again, the main display will show frequency and vice display will show duty cycle.

Measure Temperature

- Connect the black test lead to the COM Terminal and the red lead to the **** Terminal;
- 2. Turn the rotary to press "SELECT" to the temperature Mode; Now the main display will show Celsius and the vice display will show Fahrenheit:
- 3. Touch the probes to the desired test points;
- 4. Read the measured temperature on the display.

*Do not input voltage at this setting.

Test NCV

- Turn the rotary to NCV position, press "SELECT" to the temperature Mode;
- 2. Hold the product and move it around, the built-in beeper will beep when the inner sensor detects AC voltage nearby. The stronger the voltage is, the quicker the beeper beeps.

Measure V.F.C

- Connect the black test lead to the COM Terminal and the red lead to the Terminal;
- 2. Turn the rotary to , long press to enter V.F.C mode, the screen will show voltage when put the test leads at the correct circuit.

Measure square wave

- 1. Connect the black test lead to the COM Terminal and the red lead to the Terminal;
- 2. Turn the rotary switch to now, and the default output frequency is 50Hz. To change the output frequency, press the SEL button.
- 3. Touch the probes to the desired test points.

*Do not input voltage at this setting.

Maintenance

Beyond replacing batteries and fuses, do not attempt to repair or service the product unless you are qualified to do so and have the relevant calibration, performance test, and service instructions.

Clean the Product

Wipe the product with a damp cloth and mild detergent. Do not use abrasives or solvents. Dirt or moisture in the terminals can affect readings. *Remove the input signals before you clean the product.

Replace the Batteries

When "F" is shown on the display, batteries shall be replaced as below: 1. Remove the test leads and turn off the product

before replacing the batteries.

- Loosen the screw on the battery door and remove the battery door.
- Replace the used batteries with new batteries of the same type.
- 4. Place the battery door back and fasten the screw.

Replace the Fuses

When a fuse is blown or do not work properly, it shall be replaced as below:

- Remove the test leads and turn off the product before replacing the fuse.
- Loosen the four screws on the back cover and the screw on the battery door, then remove the battery door and the back cover.
- Replace the fuse with a new fuse of the same type.
- Place the back cover and the battery door back and fasten the screws.

Specifications

General Specifications		
Display (LCD) 9999 Counts		
Ranging	Auto/Manual	
Material	ABS+TPE	
Update Rate 3 Times/Secon		
Ture RMS V		
Data Hold V		
Backlight √		
Low Battery Indication √		
Auto Power Off √		

Mechanical Specifications				
Dimension 147*76*37mm				
Weight	191g (without batteries)			
Battery Type	1.5V AAA Battery * 3			
Warranty	One year			

Environmental Specifications			
0	Temperature	0~40°C	
Operating	Humidity	<75%	
6:	Temperature	-20~60°C	
Storage	Humidity	<80%	

Electrical Specifications

Function	Range	Resolution	Accuracy
	999.9mV	0.1mV	
DC Voltage	9.999V	0.001V	
(V)	99.99V	0.01V	± (0 F% + 2)
	999.9V	0.1V	±(0.5%+3)
DC Voltage	9.999mV	0.001mV	
(mV)	99.99mV	0.01mV	
	999.9mV	0.1mV	
AC Voltage	9.999V	0.001V	
(V)	99.99V	0.01V	1/1 00(. 2)
	750.0V	0.1V	±(1.0%+3)
AC Voltage (mV)	9.999mV	0.001mV	
	99.99mV	0.01mV	
*Frequency response of ACV: 40Hz-1kHz			

Function	Range	Resolution	Accum
DC Current	9.999A	0.001A	Accuracy
(A/mA)	999.9mA	0.1mA	
	99.99mA	0.01mA	
DC Current	9.999mA	0.001mA	±(1.0%+3)
(µA/mA)	99.99μΑ	0.01μΑ	
	999.9μΑ	0.1μΑ	
AC Current	9.999A	0.001A	
(A/mA)	999.9mA	0.1mA	
	99.99mA	0.01mA	+/1 20/+2\
AC Current (μA/mA)	9.999mA	0.001mA	±(1.2%+3)
	99.99μΑ	0.01μΑ	
	999.9μΑ	0.1μΑ	

Frequency response

Function	Range	Resolution	Accuracy
	99.99Ω	0.01Ω	±(1.0%+3)
	999.9Ω	0.1Ω	
	9.999kΩ	0.001kΩ	. (0 = 0 (0)
Resistance	99.99kΩ	0.01kΩ	±(0.5%+3)
	999.9kΩ	0.1kΩ	
	9.999ΜΩ	0.001ΜΩ	±(1.5%+3)
	99.99ΜΩ	0.01ΜΩ	±(3.0%+5)
	9.999nF	0.001nF	±(5.0%+20)
	99.99nF	0.01nF	
	999.9nF	0.1nF	
Capacitance	9.999µF	0.001μF	±(2.0%+5)
	99.99μF	0.01μF	
	999.9μF	0.1μF	
	9.999mF	0.001mF	±(5.0%+5)

Function			
The state of the s	Range	Resolutio	1
Frequency (Measures only to 100kHz under the ACV setting)	9.999Hz	0.001Hz	n Accurac
	99.99Hz	0.01Hz	
	999.9Hz	0.1Hz	±(0.1%+2)
	9.999kHz	0.001kHz	
	99.99kHz	0.01kHz	
	999.9kHz	0.1kHz	
	5.000MHz	0.001MHz	
Duty Cycle	1%~99%	0.1%	±(0.1%+2)
Tamanavatura	(-20~1000)°C	1°C	±(2.5%+5)
Temperature	(-4~1832)°F	1°F	1(2.3/0+3)
Diode	V		
Continuity	V		
NCV	V		
Square wave	V		
V.F.C	V		