




The best sensing distance of **1-3 meters.**


Can sense the best distance to 1-3 meters ,  
Sensing angle of **120°**




### 1. Adjustable delay time 10S-15Min



### 2. Clear the install surface.



### 3. Connectiong



### 4. Select the installation location of the sensor (A/B: required no obstruction around)

