Temperature and Humidity Sensor

Temperature Measuring Range: -10°C ~ +85°C

Humidity Measuring Range: 0 ~ 100%RH

Storage Temp.: -65°C ~ +150°C

Operating Voltage: 2.2 – 3.6V

Weight: 26g

Length: 0.5m